Forklifts: Preventing Tipping

Centrifugal and gravitational forces will cause the forklift to tip over at speeds in excess of recommendations. Forklifts are also designed with specified load limits for the forks. A loading plate for loading reference is usually located on the forklift.